

Appendix One - Photographs

Property One: before and after photos

The standard was particularly poor but after the intervention of the EH team significant improvements were made and the property could be licensed.

Before







After





Second Property – good standards



